

SB MTB-44-01, NEW ISSUE

Aeronet Galaxy Aerospace > Modifications > Edit — Mozilla Firefox

https://galaxy.aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no8

AD/SB ID: 9416

Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: CABIN SYSTEMS - AVANCE L3 SYSTEM WIRING MODIFICATION TO PREVENT TCAS FAIL MESSAGE

Title/Subject: MTB-44-01 NEW ISSUE

Version No:

Reason For Raising:

URL:

Date: 07 06 2021

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

	Title	Filename
+	MTB-44-01, NEW ISSUE	9416-2415.pdf

Aeronet Galaxy Aerospace > Modifications > Update — Mozilla Firefox

https://galaxy.aerospace.aeronet.nz/index.html

AD/SB ID: 9416

Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
	9M-PTA	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-PTB	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-PTC	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-PTD	Not Applicable	-		0	-	-	NOT APPLICABLE
	9M-PTE	Not Applicable	-		0	-	-	NOT APPLICABLE