

MTB -27-02, NEW ISSUE

Aeronet Galaxy Aerospace > Modifications > Update - Mozilla Firefox

https://galaxyaerospace.aeronet.nz/index.html

AD/SB ID: 9506 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: FLIGHT CONTROLS- INSTALLATION OF POWER LEVER POSITION AND ELEVATOR CONTROL POSITION POTENTIOMETER BRACKETS WITH FDR INSTALLED

Title/Subject: MTB -27-02, NEW ISSUE

Version No:

Reason For Raising:

URL:

Date: 16 09 2021

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
	MTB -27-02, NEW ISSUE	9506-2493.pdf

AD/SB ID: 9506 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-PTA		-		0	-	-	NOT APPLICABLE	
	9M-PTB		-		0	-	-	NOT APPLICABLE	
	9M-PTC		-		0	-	-	NOT APPLICABLE	
	9M-PTD	On Condition	-		0	-	-	OPTIONAL	
	9M-PTE	On Condition	-		0	-	-	OPTIONAL	