

HIGHLIGHT

MTC MTCPM-BB1-HIGHLIGHT

Publication Title MTC EC155 B-B1
NR010

Publication Date 2021.07.21

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
MTC 00-00-00	LIST OF ILLUSTRATIONS	N	2021.07.21			
MTC 00-00-00	INTRODUCTION	R	2020.09.18			
MTC 20-01-01-102	List of consumable materials - Miscellaneous products used on helicopters	R	2021.07.01	I	Information added	No
MTC 20-01-01-301	Use of greases - Miscellaneous products used on helicopters	R	2021.07.01	I	Information added	No
MTC 20-01-01-302	Use of oils - Miscellaneous products used on helicopters	R	2021.06.30	I	Information added	No
MTC 20-01-01-304	Use of special products - Miscellaneous products used on helicopters	R	2021.06.30	I	Information added	No
MTC 20-01-01-306	Use of liquid fuels - Miscellaneous products used on helicopters	R	2021.06.29	I	Information added	No
MTC 20-02-05-404	Assembly by screws and nuts - Joining	R	2021.07.07	C	Discrepancy corrected	Yes
MTC 20-02-08-405	Replacement of "ROSAN" sockets and studs - Replacement of components on structure and mechanical assemblies	R	2021.07.06	I	Information added	No
MTC 20-02-08-406	Replacement and installation of inserts in honeycomb panels - Replacement of components on structure and mechanical assemblies	R	2020.10.02	I	Information added	No

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
MTC 20-02-08-407	Installation of blanks on vortex tubes and outflow nozzles on engine air intake filter - Replacement of components on structure and mechanical assemblies	R	2020.09.17	I	Information added	No
MTC 20-02-08-408	Installation and crimping of vortex tubes and outlet cones on engine air intake filter - Replacement of components on structure and mechanical assemblies	R	2020.09.17	I	Information added	No
MTC 20-03-04-409	Replacement of a quick-release fastener ECS7145 - Replacement of miscellaneous components	N	2020.10.08	R	New document unit	No
MTC 20-03-05-404	Crack stop-drilling and repair principle - Scores - Cracks - Perforations	R	2020.09.30	I	Information added	No
MTC 20-03-06-406	Structural repairs: Vacuum bag techniques - Structural repairs	R	2020.10.08	I	Information added	No
MTC 20-03-06-420	Repair of dent on a cowling or a fairing - Structural repairs	R	2020.09.29	I	Information added	No
MTC 20-03-06-423	Repair of wrinkling on a cowling or a Fairing - Structural repairs	R	2020.09.29	I	Information added	No
MTC 20-03-06-430	Repair of hole drilled outside an insert on a cowling or a fairing - Structural repairs	R	2020.09.29	I	Information added	No

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
MTC 20-03-06-437	Repair following anomalies on honeycomb edge on cowling or fairing - Structural repairs	R	2020.09.30	I	Information added	No
MTC 20-03-06-438	Repair of incorrect compacting on cowling or fairing - Structural repairs	R	2020.09.29	I	Information added	No
MTC 20-04-04-404	Touch-up of protective treatment (phosphating and black anodizing) - Surface treatment before painting	R	2021.07.05	I	Information added	No
MTC 20-04-05-101	Painting equipments and paint touch-ups - General - Paint and primer application procedure	R	2021.07.07	I	Information added	Yes
MTC 20-04-07-401	Application of Marking Media and Decorations - Paint and Primer Application Procedure	R	2021.07.07	I	Information added	No
MTC 20-05-01-103	Equivalences and replacement of sealing compounds - General sealing procedures	R	2021.07.05	I	Information added	No
MTC 20-05-01-222	Application of PR 1771 B2 sealant - General sealing procedures	R	2021.06.30	I	Information added	No
MTC 20-05-01-223	Application of PR 1776 B2 / 1776 S sealing compounds - General sealing procedures	R	2021.07.08	I	Information added	No
MTC 20-05-01-401	Use of THIXOFLEX and SLG products - General sealing procedures	R	2021.07.05	C	Discrepancy corrected	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
MTC 20-06-04-305	Application of mixtures No. 16 and No. 17 - Use of bonding mixtures	R	2021.06.28	I	Information added	No
MTC 20-07-02-202	Aircraft refueling from a tanker - Safety instructions	R	2021.07.05	C	Discrepancy corrected	Yes
MTC 20-07-02-212	Recommendations for working at height - Human Factors Approach - Safety instructions	N	2021.07.08	R	New document unit	Yes
MTC 20-08-05-101	Drafting and updating the log card (FM) - General rules applicable to aircraft	R	2021.06.30	I	Information added	No
MTC 20-08-05-107	Recommendations for technical requests - General rules applicable to aircraft	N	2020.11.18	R	New document unit	No
MTC 20-08-05-108	MGB oil sampling method to check the water content - General rules applicable to aircraft	N	2021.06.30	R	New document unit	No
MTC 20-08-06-403	Use of biocide products - Organic contamination of jet fuels, monitoring, detection and remedial action	R	2021.07.07	I	Information added	No
MTC 20-09-00-102	DELETED	D	2016.07.05			
MTC 20-09-01-901	Storage of helicopters. - Storage	R	2021.07.08	R	New document unit	No
MTC 20-09-01-906	DELETED	D	2014.01.28			
MTC 20-09-02-907	Check and scheduled servicing of removed and stored assemblies - Preservation	N	2021.07.08	R	New document unit	No

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
MTC 20-60-00-101	Preparation of polyurethane ink XD 150 - Blade standard practices	R	2021.07.06	I	Information added	No
MTC 20-60-00-432	Audio control procedure by blade tapping - Blade standard practices	R	2021.07.05	I	Information added	Yes
MTC 20-60-00-439	Completing blade inspection reports - Blade standard practices	R	2021.07.07	C	Discrepancy corrected	No
MTC 20-80-20-101	Contact insertion and extraction method and tools - Standard Practices - Electrical Power	R	2021.07.02	I	Information added	No
MTC 20-80-20-401	Presentation of repair kits for installation on non-shielded cables - Standard Practices - Electrical Power	R	2021.06.23	I	Information added	Yes
MTC 20-80-20-425	Tools and settings associated with the crimping of contacts - Standard Practices - Electrical Power	R	2021.07.08	I	Information added	No
MTC 20-80-20-432	Tools and processes associated with the Triaxial Radial connector RTX 004 M 02 - EN3716-004M2 - Standard Practices - Electrical Power	R	2021.06.23	I	Information added	No
MTC 20-80-20-441	Installation of electrical cable bundles and optical fibres - Standard Practices - Electrical Power	R	2020.09.29	F	Form changed	No

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION