



MYCOPTER AVIATION SERVICES SDN.BHD.  
 LOT 10, HELICOPTER CENTRE,  
 MALAYSIA INTERNATIONAL AEROSPACE CENTRE,  
 SULTAN ABDUL AZIZ SHAH AIRPORT,  
 47200 SUBANG, SELANGOR, MALAYSIA

# WORKSHEET

WORKSHEET NUMBER: WS-038  
 ISSUE DATE: 14.10.2021

AIRCRAFT TYPE:	AW139	AIRCRAFT	#1 ENGINE	#2 ENGINE
AIRCRAFT REGISTRATION:	N917YB	HOURS	300:40	300:40
AIRCRAFT SERIAL NUMBER:	31763	LDG CYCLE	838	
#1 ENGINE SERIAL NUMBER:	PCE-KB1931	HOIST	414	
#2 ENGINE SERIAL NUMBER:	PCE-KB1885	HEC	-	
REASON FOR RAISING AIRCRAFT SHORT TERM STORAGE (FLYABLE STORAGE) AND SERVICE BULLETIN NEED TO BE CARRIED OUT I.A.W. CHAPTER 4 AND CHAPTER 5 - AMPI (FAA) - IETP 39th ISSUE 07 JUN 2021 (UPDATED: 20 JUL 2021) <b>ISSUE 40 DATED 10-12-2021</b>		ENGINE START CYCLE	261	261

## AIRCRAFT SHORT TERM STORAGE (FLYABLE STORAGE) AND AIRCRAFT SERVICE BULLETIN

ITEM	TASK/DESCRIPTION	REFERENCE	TECHNICIAN	INSPECTOR	DATE
01	GROUND RUN HAS BEEN PERFORMED ON: <b>10-12-2021</b> NO AIRCRAFT ACTIVITY SINCE LAST ENGINE GROUND RUN. PERFORM FLYABLE STORAGE - (INITIAL) PRESERVATION PROCEDURE I.A.W. AMP 39-A-10-31-00-00A-810A-A. REMARKS:	AMP 39-A-10-31-00-00A-810A-A			<b>10-12-2021</b>
02	PERFORM LEONARDO SB 139-452, REVISION B, PART 1 : MAIN ROTOR DAMPER INSPECTION AND REPLACEMENT. DUE: AFTER LAST FLIGHT (ALF) (RECURRENT EVERY ALF) REMARKS:	SB 139-452, REVISION B			<b>10-12-2021</b>