

**PARA 14 – COMPLIED WITH (5 M/R DAMPERS REPLACED WITH P/N 3G6220V01353)**

AD/SB ID: 11030 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC		-		0	-	-	COMPLIED WITH	
	9M-BOD		-		0	-	-	COMPLIED WITH	

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft\_templates&opener\_name=aircraft&mode=edit&template=no&opener\_form\_name=ed...

AD/SB ID: 11030 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: ADS  Repetitive

Reference/Number: ATA 62 - MAIN ROTOR - MAIN ROTOR DAMPER - INSPECTION / REPLACEMENT

Title/Subject: AD NO. 2018-0112R1 PARA 14(SB 139-452 PART II)

**9M-BOC**

<b>3G6220V01353</b> <b>MAIN ROTOR DAMPER [Position: White] [Limitation Type: Overhaul]</b>	<b>MCR6522</b>
<b>3G6220V01353</b> <b>MAIN ROTOR DAMPER [Position: Blue] [Limitation Type: Overhaul]</b>	<b>MCR12982</b>
<b>3G6220V01353</b> <b>MAIN ROTOR DAMPER [Position: Red] [Limitation Type: Overhaul]</b>	<b>MCR8174</b>
<b>3G6220V01353</b> <b>MAIN ROTOR LAG DAMPER [Position: Orange] [Limitation Type: Overhaul]</b>	<b>2157</b>
<b>3G6220V01353</b> <b>MAIN ROTOR DAMPER [Position: Black] [Limitation Type: Overhaul]</b>	<b>MCR6111</b>

**9M-BOD**

<b>3G6220V01353</b> <b>MAIN ROTOR DAMPER</b> [Position: Black] [Limitation Type: Overhaul]	<b>1130</b>
<b>3G6220V01353</b> <b>MAIN ROTOR DAMPER</b> [Position: White] [Limitation Type: Overhaul]	<b>MCR6110</b>
<b>3G6220V01353</b> <b>MAIN ROTOR DAMPER</b> [Position: Blue] [Limitation Type: Overhaul]	<b>MCR12226</b>
<b>3G6220V01353</b> <b>MAIN ROTOR DAMPER</b> [Position: Red] [Limitation Type: Overhaul]	<b>MCR2855</b>
<b>3G6220V01353</b> <b>MAIN ROTOR DAMPER</b> [Position: Orange] [Limitation Type: Overhaul]	<b>MCR2799</b>