

Tech Query + Repair Instr Query - PSE/TQ/2021/34532

### **Document Reference**

Document ID	PSE/TQ/2021/34532	Contact	Adi Harith Mohd Tahir
Your Code Reference	JBPM	Subject	Technical Query : Hydraulic Pipes Part Number confirmation
Topic	TECHNICAL	Subtopic	OTHER
Issue	SEE TQ DETAIL	Team Legal Entity	Italy

### **Contact Details**

Customer Description	GALAXY HELICOPTERS(M) SDN BHD	Customer ID	0050007871
Email	adiharith@galaxyaerospace.my		

# **Contacts List**

First Name	Last Name	Email	User Type
MUHAMMAD IHSAN	MASRI	ihsan@galaxyaerospace.my	Lead Technician
Ezhan Izzad	Mohd Nor	ezhan@galaxyaerospace.my	Engineer in Charge
YASIR	SHAPUAN	yasir@galaxyaerospace.my	Engineer in Charge
Ahmad Akmal Alif	Abdul Aziz	akmalalif@galaxyaerospace.my	Engineer in Charge

# **Customer Service**

Priority	Routine	Creation On (UTC)	09/07/2021
Resolve By (UTC)	19/07/2021	Leonardo Closure Date (UTC)	09/07/2021

## **Helicopter Data**

ATA Code	00	Description	AIR VEHICLE GENERAL
Helicopter S/N	NC0011212	Aircraft Tail Number	9M-BOB
Helicopter Line	AW109/119	Helicopter Model	A109E
Repair Istruction Query	False		

Part Number	Component S/N	Component F/H	On (Date)(UTC)

Flight Hours	FH Last Update	Create date
3555,15	15/06/2021	15/06/2021

# **Ticket Description**

Dear Sir,

Good day to you.

Regarding to EASA AD 2007-0231 (as per attachment), the Hydraulic Pipes with P/N 109-0761-64-103 and P/N 109-0761-65-103 are applicable with this AD. Unfortunately, we can't determine the information either

this helicopter fitted with this hydraulic pipes's Part Number or not. With respect to this matter kindly need your assistance to advise and confirm the Part Number for Hydraulic Pipes that fitted on helicopter as per below:
Aircraft Trans Laurende Hellingster A100F

Aircraft SN: 11212 Aircraft Reg: 9M-BOB

Best Regard,

Adi Harith Mohd Tahir

Technical Services Engineer

## **History Log**

## **Closing Note**

Dear Adi,

Firstly, please be informed that EASA AD 2007-0231 cross refers SB109EP-73 and this SB is not applicable to your MSN

This is because in production your H/C has been equipped with P/N 109-0763-96-101 and P/N 109-0763-97-101.

Best regards, Dhana

### **Ticket Attachments**

Attachment's Name	Uploading Date
EASA_AD_2007-0231_1_20210315.pdf	09/07/2021