

PRATT & WHITNEY CANADA
TOOL SERVICE BULLETIN

NO: PT-987

Service Tool: PWC32486 Rev. NC2

Description: Socket - Nut

Effectivity: PT6A-21, PT6A-25, PT6A-25C, PT6A-34, PT6A-38, PT6A-50, PT6A-52, PT6A-62, PT6A-64, PT6A-65SC, PT6A-66, PT6A-66D, PT6A-67A, PT6A-67B, PT6A-67D, PT6A-67F, PT6A-67RM, PT6A-68, PT6A-68B, PT6A-68C, PT6A-68D, PT6A-140, PT6A-140A, PT6A-140AG, PT6B-37A, PT6B-67A, PT6C-67C, PT6C-67D, PT6C-67E, PT6E-67XP

Subject: Tool obsolete

Reason:

Problem: Unable to use socket on oil tray.

Cause: Outer diameter of socket can be very large to fit properly.

Solution: Obsolete, replaced by PWC72243.

WARNING - PROPRIETARY RIGHTS & EXPORT CONTROLS NOTICE

This bulletin contains proprietary information of Pratt & Whitney Canada Corp. ("P&WC"), which P&WC provides in confidence and solely for the purposes of supporting engine certification and providing applicable information regarding the proper use, maintenance, inspection, repair, servicing and parts application of P&WC products and services, as directed therein. Neither this bulletin nor any information in it may be disclosed to others, or used for any other purpose, including, without limitation, to design, create, develop, reproduce, manufacture or derive any design, part, product, material, process, modification, configuration change or repair, or obtain FAA or other government approval to do so. Possession and use of this bulletin is also subject to the restrictions set out in P&WC's Technical Data Agreement (a copy of which may be obtained by contacting P&WC Technical Publications). The contents of this bulletin may be subject to export control laws. Unauthorized export or re-export of the bulletin, or parts thereof, is prohibited. By accepting and possessing this bulletin, you agree to be bound by the foregoing terms.

If a Government agency or department intends to disclose any information, written notice should be given to:
VP - Legal Services, Pratt & Whitney Canada Corp., 1000 Marie-Victorin (01BE5), Longueuil, Quebec J4G 1A1.

Issued: Jun 15/2021

PWC32486
Page 1 of 2

PRATT & WHITNEY CANADA
TOOL SERVICE BULLETIN

NO: PT-987

Instruction: Tool PWC32486 is obsolete, replaced by PWC72243.

Compliance: Optional

Tool Usage: Overhaul, Heavy Maintenance

Tool Disposition: Tool PWC32486 is still usable but no longer procurable.

Issued: Jun 15/2021

P&WC Proprietary Information. Subject to the restrictions on the first page.

PWC32486
Page 2 of 2