



D212-1 HYDRAULIC SERVO ASSEMBLY [Limitation Type: Overhaul]	33711	Airframe Hours	2400
D212-1 HYDRAULIC SERVO ASSEMBLY [Limitation Type: Overhaul]	33618	Airframe Hours	2400
D212-1 HYDRAULIC SERVO ASSEMBLY	33712	Airframe Hours	2400

R44 SB 109  HYDRAULIC CONTROLS PRE-TAKEOFF CHECK	Not Applicable	-	-	-	-	NOT APPLICABLE 
--	----------------	---	---	---	---	--

Edit Limitation R44 SB 109 -HYDRAULIC CONTROLS PRE-TAKEOFF CHECK

Based On:	Not Applicable <input type="button" value="v"/>
Warning:	<input type="text" value="0"/>
Warning Unit:	Select <input type="button" value="v"/>
Completed:	<input type="text" value="-"/>
Due At:	<input type="text" value="0.00"/>
Status:	NOT APPLICABLE <input type="button" value="v"/>
Limitation Notes:	<div style="border: 1px solid gray; padding: 5px;"> <p>REFER TIC-R44-21-0008 DATED 01/07/2021.</p> <p>NOT APPLICABLE DUE TO ALL R44 CADETS WERE FACTORY FITTED WITH UNAFFECTED SERVOS.</p> </div>