

TIC-AW139-21-0278

SB NO 139-474, NEW ISSUE

ATA 97 - INSTALLATION OF MAX VIZ UNDER FUSELAGE

AD/SB ID: 8601

General Config List Aircraft List Task List Linked To BOM

Type : SBS  Repetitive

Reference/Number: ATA 97 - INSTALLATION OF MAX VIZ UNDER FUSELAGE

Title/Subject: SB NO 139-474, NEW ISSUE

Version No:

Reason For Raising:

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BFU	On Condition	-		0	-	-	Required	
	9M-BOC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOD	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-JPM	On Condition	-		0	-	-	OPTIONAL	
	9M-PMA	On Condition	-		0	-	-	OPTIONAL	
	9M-PMB	On Condition	-		0	-	-	OPTIONAL	
	9M-PMC	On Condition	-		0	-	-	OPTIONAL	
	9M-PMD	On Condition	-		0	-	-	OPTIONAL	
	9M-PME	On Condition	-		0	-	-	OPTIONAL	

Edit Limitation

Linked To:

Based On:

Warning:

Warning Unit:

Completed:

Due At:

Status:

Limitation Notes:

OPTIONAL SB: APPLICABLE. COMPLY UPON CUSTOMER REQUEST.  
REFER TIC-AW139-21-0278  
DATED 25.08.2021