

HELICOPTERS DIVISION

TECHNICAL INFORMATION LETTER

TIL N°	T-169-21-006
	T-189-21-002
DATE:	October 21, 2021
REV.:	/

To:	Leonardo Helicopters products Owners / Operators / Service Centres	
SUBJECT:	Thermal Strip PN M06SHA094D01R1	
Helicopters Affected:	AW169, AW189	

Dear Customer/Operator,

Leonardo Helicopters (LH) wishes to provide you with additional information on the thermal strip P/N M06SHA094D01R1 installed on tail rotor duplex bearing spacer P/N MM6430A00151 installed on AW169 and AW189 helicopters or kept in stock.

LH would like to highlight that the applicable thermal strip is made by yellow/brownish boxes turning to black colour when triggered by a specific temperature, as shown in the picture here below:



BEFORE ACTIVATION

AFTER ACTIVATION AT 104

2mm

32mm

In order to support the Operators during the accomplishment of the temperature check on the thermal strip requested by SB169-178 and SB189-272, the aforementioned information, already available on the component data sheet, will be added at the first suitable occasion in the relevant AMP Data Module of AW169 and AW189 IETP.

Should you need any additional information, please do not hesitate to refer to the point of contact provided with the Customer Support & Training Worldwide Directory, available on Leonardo Customer Portal at this <u>link</u>.

Yours Sincerely,

Jabriele

Gabriele Bordino Head of Product Support Engineering

Page 2 of 2	TIL N° :	T-169-21-006 T-189-21-002
	Date :	October 21, 2021
	Rev :	1