

**TIC-172S-22-0005**

**9M-PST & 9M-PSU**

AD/SB ID: 7242 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type : ADS  Repetitive

Reference/Number: RECIPROCATING ENGINE POWER SECTION.

Title/Subject: 2017-16-11 [ADMT 39-18988]

Version No:

Reason For Raising: IDENTIFICATION OF CONNECTING RODS WITH NON CONFORMING SMALL END BUSHINGS

AD/SB ID: 7242 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-PST	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PSU	Not Applicable	-		0	-	-	NOT APPLICABLE	

**9M-PSR**

AD/SB ID: 1872 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type : ADS  Repetitive

Reference/Number: RECIPROCATING ENGINE POWER SECTION.

Title/Subject: AD 2017-16-11 (ADMT 39-18988)

Version No:

Reason For Raising: IDENTIFICATIONS OF CONNECTING RODS WITH NON-CONFORMING SMALL END BUSHINGS. NOTED.

AD/SB ID: 1872 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-PSR	Not Applicable	-		0	-	-	NOT APPLICABLE	

**9M-PSS**

AD/SB ID: 6432 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type : ADS  Repetitive

Reference/Number: RECIPROCATING ENGINE POWER SECTION.

Title/Subject: AD 2017-16-11 (ADMT 39-18988)

Version No:

Reason For Raising: INDENTIFICATIONS OF CONNECTING RODS WITH NON-CONFORMING SMALL END BUSHINGS. NOTED.

AD/SB ID: 6432 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-PSS	Not Applicable	-		0	-	-	NOT APPLICABLE	