

# TIC-AW189-21-0114

AD/SB ID: 9577 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS  Repetitive

Reference/Number: ATA 34 - GLIDE SLOPE ANTENNA INSPECTION

Title/Subject: SBA 189-295 NEW ISSUE, PART I

Version No:

AD/SB ID: 9577 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOE	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOF	Not Applicable	-		0	-	-	NOT APPLICABLE	

AD/SB ID: 9578 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS  Repetitive

Reference/Number: ATA 34 - GLIDE SLOPE ANTENNA INSPECTION

Title/Subject: SBA 189-295 NEW ISSUE, PART II

Version No:

AD/SB ID: 9578 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOE	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOF	Not Applicable	-		0	-	-	NOT APPLICABLE	