

TIC-AW189-21-0115

galaxyaerospace.aeronet.nz/index.html

AD/SB ID: 9587 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type : SBS Repetitive

Reference/Number: ATA 34 - GLIDE SLOPE ANTENNA INSPECTION

Title/Subject: SB NO. 189-295, NEW ISSUE (ERRATA CORRIGE)

Version No:

Reason For Raising:

AD/SB ID: 9587 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOE	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOF	Not Applicable	-		0	-	-	NOT APPLICABLE	