

TIC-AW189-21-0132

Edit Limitation (A/C: 9M.BOE)	
Edit Limitation SB NO. 189-245, NEW ISSUE-ATA 33 - INSPECTION AND REINFORCE... [X] Cancel [Save]	
Based On:	Select ▼
Warning:	0
Warning Unit:	Select ▼
Completed:	-
Due At:	0.00
Status:	NOT APPLICABLE ▼
Limitation Notes:	NOT APPLICABLE TO THIS AIRCRAFT BECAUSE AIRCRAFT IS NOT EQUIPPED WITH AFFECTED PART NUMBER KIT SEARCHLIGHT (A800) SYSTEM P/N 8G3340F00811

Edit Limitation (A/C: 9M.BOF)	
Edit Limitation SB NO. 189-245, NEW ISSUE-ATA 33 - INSPECTION AND REINFORCE... [X] Cancel [Save]	
Based On:	Select ▼
Warning:	0
Warning Unit:	Select ▼
Completed:	-
Due At:	0.00
Status:	NOT APPLICABLE ▼
Limitation Notes:	NOT APPLICABLE TO THIS AIRCRAFT BECAUSE AIRCRAFT IS NOT EQUIPPED WITH AFFECTED PART NUMBER KIT SEARCHLIGHT (A800) SYSTEM P/N 8G3340F00811