

TIC-A109E-22-0013

AD/SB ID: 9904 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type : SBS Repetitive

Reference/Number: TURBOSHAFT ENGINE - COMPRESSOR CENTRIFUGAL IMPELLER - REPLACEMENT/MODIFICATION OF

Title/Subject: SB NO. 28306, REVISION 4

AD/SB ID: 9904 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOB		-		0	-	-	Category 7	