

TIC-A109E-22-0028

ADS	<input checked="" type="checkbox"/> Repetitive
ATA 53 FUSELAGE CENTRE FUSELAGE FRAME ASSEMBLY INSPECTION / REPAIR (EVERY 100 FH)	
EASA AD NO. 2020-0153 (SB109EP-173 REV.A PART I)	
Linked To:	9M-BOB
Based On:	Airframe Hours
Period:	100
Warning:	50
Warning Unit:	Hours
Last Done:	3661.51
Next Due:	3761.51
Limitation Notes:	LAST COMPLIED @ 3661:30 FH ON 26.11.2021 REFER 9M-BOB-8470 TIC-A109E-22-0028 APPLICABLE TO THIS AIRCRAFT TYPE COMPLIANCE: IF LESS THAN 1000 FH AND LESS THAN 2000 LANDINGS WITHIN 100 FH UPON ACCUMULATION OF 1000