

TIC-AW139-22-0193

AD/SB ID: 10093 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: DRIVE PULLEY WASHER INSPECTION

Title/Subject: SB NO. 139-692, NEW ISSUE

AD/SB ID: 10093 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BFU		-		0	-	-	Required	
	9M-BOC		-		0	-	-	NOT APPLICABLE	
	9M-BOD		-		0	-	-	NOT APPLICABLE	