

TIC-AW139-22-0236

AD/SB ID: 10149 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: ATA 64 - TAIL ROTOR DUPLEX BEARING REPETITIVE INSPECTIONS

Title/Subject: SB 139-728 REV/ PART I

AD/SB ID: 10149 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOC	Airframe Hours	50	Hours	10	3506.15 ↕	3556.15 ↕	Required	
	9M-BOD	Airframe Hours	50	Hours	10	0.00 ↕	3563.75 ↕	Required	