

TIC-AW139-22-0256

9M-BOC & 9M-BOD (ENGINE 1)

AD/SB ID: 9304 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF

Title/Subject: NO.1 ENGINE ~ SB NO. 41121 REV.2

AD/SB ID: 9304 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BFU	On Condition	-		0	-	-	Required	
	9M-BGH	On Condition	-		0	-	-	Category 5	
	9M-BOC	On Condition	-		0	-	-	Category 5	
	9M-BOD	On Condition	-		0	-	-	Category 5	

9M-BOC & 9M-BOD (ENGINE 2)

AD/SB ID: 9303 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: PT6C-67C SERVICE BULLETIN - HOUSINGS FOR ACCESSORY GEARBOX AND INLET CASE - IDENTIFICATION OF

Title/Subject: NO. 2 ENGINE ~ SB NO. 41121 REV.2

AD/SB ID: 9303 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BFU	On Condition	-		0	-	-	Required	
	9M-BGH	On Condition	-		0	-	-	Category 5	
	9M-BOC	On Condition	-		0	-	-	Category 5	
	9M-BOD	On Condition	-		0	-	-	Category 5	