

SB NO. 28404, REV 1 - ENG 1

| Aircraft | Based On | Period | Warning Unit | Warning | Last Done | Next Due | Status |
|----------|--------------|--------|--------------|---------|-----------|----------|------------|
| 9M-BOB | On Condition | - | | 0 | - | - | Category 7 |

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy.aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=...

AD/SB ID: 10326

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference/Number: TURBOHAFT ENGINE NOZZEL - ASSEMBLY TURBINE EXHAUST - REPLACEMENT

Title/Subject: SB NO. 28404, REV 1 - ENG 1

Version No:

Reason For Raising:

URL:

Date: 29 / 03 / 2023

Edit Limitation SB NO. 28404, REV 1 - ENG 1-TURBOHAFT ENGINE NOZZEL - ASSE...

Based On: On Condition

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: Category 7

Limitation Notes:

REFER TIC-A109E-23-0010

THIS SB IS ISSUED TO PROVIDE INSTRUCTION FOR REPLACEMENT OF NO 5 COVER BEARING HOUSING WITH NEW PART THAT HAS INFRARED HOLES DIAMETER TO MEET BRAZING SPECIFICATION REQUIREMENTS.

COMPLIANCE: CAT 7, TO COMPLY WITH WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED

SB NO. 28404, REV 1 - ENG 2

ADI SB ID: 10327 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

| Aircraft | Based On | Period | Warning Unit | Warning | Last Done | Next Due | Status |
|----------|--------------|--------|--------------|---------|-----------|----------|------------|
| 9M-BOB | On Condition | - | | 0 | - | - | Category 7 |

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=editform&template_id=1...

ADI SB ID: 10327 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference Number: TURBOSHIFT ENGINE NOZZEL - ASSEMBLY TURBINE EXHAUST - REPLACEMENT

Title/Subject: SB NO. 28404, REV 1 - ENG 2

Version No:

Reason For Raising:

URL:

Date: 29 / 03 / 2023

Edit Limitation SB NO. 28404, REV 1 - ENG 1-TURBOSHIFT ENGINE NOZZEL - ASSE... Cancel Save

Based On: On Condition

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: Category 7

Limitation Notes:

REFER TIC-A109E-23-0010

THIS SB IS ISSUED TO PROVIDE INSTRUCTION FOR REPLACEMENT OF NO 5 COVER BEARING HOUSING WITH NEW PART THAT HAS INFRARED HOLES DIAMETER TO MEET BRAZING SPECIFICATION REQUIREMENTS.

COMPLIANCE: CAT 7, TO COMPLY WITH WHEN THE SUPPLY OF SUPERSEDED PARTS IS FULLY USED