

TIC-AW189-23-0048

AD NO. 2021-0131, REV 1

NOT APPLICABLE DUE TO AIRCRAFT NOT MODIFIED WITH EASA STC 10061971.

The screenshot displays a web-based interface for managing aircraft modifications. The top window shows a table of modifications for AD/SB ID: 10315. The table has columns for Aircraft, Based On, Period, Warning Unit, Warning, Last Done, Next Due, and Status. Two entries are visible: 9M-BOE and 9M-BOF, both with a status of 'NOT APPLICABLE'.

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOE		-		0	-	-	NOT APPLICABLE
9M-BOF		-		0	-	-	NOT APPLICABLE

The bottom window shows the 'Edit' form for a modification. The 'Type' is set to 'ADS' and 'Repetitive' is unchecked. The 'Reference/Number' field contains 'ATA 11 - PLACARDS AND MARKINGS - STRETCHER UNIT / PLACARDS - INSTALLATION'. The 'Title/Subject' field contains 'EASAAD NO. 2021-0131 REV. 1'. The 'Version No.' field is empty.