

TIC-AW189-23-0068

For 9M-BOE, this SB will be carried out during 400FH // 1Y Inspection; 1562:32 FH // 17-Aug-2023.

For 9M-BOF, this SB will be carried out within 1 year after this issue of this SB; 28-May-2024.

The screenshot displays a software interface for managing aircraft modifications. The top window shows a table with columns: Aircraft, Based On, Period, Warning Unit, Warning, Last Done, Next Due, and Status. Below this, a second window provides a detailed view of a task, including fields for Type, Reference Number, and Title/Subject.

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOE	Date (Years)	- Days		80	-	17/08/2023	TO BE COMPLIED
9M-BOE	Airframe Hours	- Hours		50	0.00	1562.53	TO BE COMPLIED
9M-BOF	Date (Years)	- Days		90	-	28/05/2024	TO BE COMPLIED

Task Details:

- Type: SBS Repetitive
- Reference Number: ATA 32 - MAIN LANDING GEAR PINTLE PIN NEW BOLTS INSTALLATION
- Title/Subject: SB NO 189-282, NEW ISSUE