

TIC-AW139-23-0022

SB NO. 139-604, REV A – NOT TO BE COMPLIED WITH AS PER OPERATOR DECISION

AD/ SB ID: 10214 Close Update Save & Close

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOC	On Condition	-		0	-	-	OPTIONAL
9M-BOD	On Condition	-		0	-	-	OPTIONAL
9M-JPM	On Condition	-		0	-	-	OPTIONAL
9M-YTL	On Condition	-		0	-	-	OPTIONAL

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy.aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=...

AD/ SB ID: 10214 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: **SBS** Repetitive

Reference Number: ATA 66 - INSTALLATION OF KIT MOORING

Title/Subject: 139-604 REV A

Version No:

Reason For Raising:

URL:

Edit Limitation (A/C: 9M-BOC)

Edit Limitation 139-604 REV A-ATA 66 - INSTALLATION OF KIT MOORING Cancel Save

Based On: On Condition

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: OPTIONAL

Limitation Notes: REFER TIC-AW139-23-0022
APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER AFFECTED.
COMPLIANCE: OPTIONAL. NOT TO BE COMPLIED WITH AS PER AOSB/18PM/23-001 DATED 14-JUN-23

Edit Limitation (A/C: 9M-BOD)

Edit Limitation 139-604 REV A-ATA 66 - INSTALLATION OF KIT MOORING Cancel Save

Based On: On Condition

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: OPTIONAL

Limitation Notes: REFER TIC-AW139-23-0022
APPLICABLE TO THIS AIRCRAFT DUE TO SERIAL NUMBER AFFECTED.
COMPLIANCE: OPTIONAL. NOT TO BE COMPLIED WITH AS PER AOSB/18PM/23-001 DATED 14-JUN-23