

TIC-AW139-23-0117

NOT APPLICABLE FOR BOTH AW139 JBPM FLEET

AD/SB ID: 10320 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BGH	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOD	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-JPM	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-SAAS	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YTL	Not Applicable	-		0	-	-	NOT APPLICABLE	

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name...

AD/SB ID: 10320 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: ADS Repetitive

Reference/Number: ATA 11 - PLACARDS AND MARKINGS - STRETCHER UNIT / PLACARDS - INSTALLATION

Title/Subject: EASA AD NO. 2023-0088, NEW ISSUE