

TIC-A109E-23-0037

PART I - TO BE COMPLIED WITH ON NEXT 200FH//12M INSPECTION

Activity	MPM 05-50-1, MPM 05-...	Airframe Hours*	200	50 Hours	3805.33	4005.33	151.43 Hours +
AF 200 FH//12 MONTHS INSPECTION Special Inspections							
AF 200 FH//12 MONTHS INSPECTION Special Inspections		Date (Months)*	12	6 Months	12/04/2023	12/04/2024	175 days +

AD/SB ID: 10583 Close Update Save & Close

General	Config List	Aircraft List	Task List	Linked To	BOM		
Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOB	Airframe Hours	200 Hours		50	0.00	4005.55	Required
9M-BOB	Date (Months)	12 Days		90	-	12/04/2024	Required

Aeronet Galaxy Aerospace > Modifications > Update - Google Chrome

galaxyaerospace.aeronet.nz/index.html

AD/SB ID: 10583 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference Number: ATA 85 - NPIR UPDATED

Title/Subject: SB NO. 105EP-182, NEW ISSUE PART I

Version No:

PART II - TO BE COMPLIED WITH WITHIN 200FH//12M (4049:07FH//10/10/2024)

AD/SB ID: 10584 Close Update Save & Close

General	Config List	Aircraft List	Task List	Linked To	BOM		
Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOB	Airframe Hours	200 Hours		50	0.00	4049.12	Required
9M-BOB	Date (Months)	12 Days		90	-	10/10/2024	Required

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name...

AD/SB ID: 10584 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference Number: ATA 85 - NPIR UPDATED

Title/Subject: SB NO. 105EP-182, NEW ISSUE PART II

PART III - TO BE COMPLIED WITH WITHIN 200FH//12M (4049:07FH//10/10/2024)

AD/SB ID: 10586 Close Update Save & Close

General	Config List	Aircraft List	Task List	Linked To	BOM		
Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOB	Date (Months)	12 Days		90	-	10/10/2024	Required
9M-BOB	Airframe Hours	200 Hours		50	0.00	4049.12	Required

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name...

AD/SB ID: 10586 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: SBS Repetitive

Reference Number: ATA 85 - NPIR UPDATED

Title/Subject: SB NO. 105EP-182, NEW ISSUE PART III

PART IV - WITHIN 2Y (10/10/2025)

AD/SB ID: 10587 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
SM-BOB	Date (Years)	2 Days		90	-	10/10/2025	Required

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=...

AD/SB ID: 10587 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference Number: ATA 85 - PPPI UPDATED

Title/Subject: SB NO.: 109EP-162 , NEW ISSUE PART IV