

TIC-AW189-23-0084

PARA 1

9M-BOE: APPLICABLE. FIRST COMPLIANCE; 9M-BOE-16669

9M-BOF: NOT APPLICABLE

AD/SB ID: 10410 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOE	Airframe Hours	50 Hours		10	1385.08 ↕	1435.08 ↕	Required	
	9M-BOF	Not Applicable	0		0	-	-	Required	

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=ed...

AD/SB ID: 10410 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: ADS Repetitive

Reference/Number: ATA 78 - ENGINE EXHAUST EJECTOR DUCT INSPECTION

Title/Subject: ASB 189-384 REV./ (EAD 2023-0149 PARA 1)

PARA 2

AD/SB ID: 11024 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOE	On Condition	-		0	-	-	ON CONDITION	
	9M-BOF	Not Applicable	-		0	-	-	NOT APPLICABLE	

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=ed...

AD/SB ID: 11024 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: ADS Repetitive

Reference/Number: ATA 78 - ENGINE EXHAUST EJECTOR DUCT INSPECTION

Title/Subject: AD NO. 2023-0149, NEW ISSUE PARA 2