

TIC-AW189-23-0082

PARA 1

9M-BOE: APPLICABLE. FIRST COMPLIANCE; 9M-BOE-16669

9M-BOF: NOT APPLICABLE

AD/SB ID: 10409

Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BOE	Airframe Hours	50	Hours	10	1385.08 ↗	1435.08 ↗	Required	🗑️
	9M-BOF	Not Applicable	25		10	-	-	Required	🗑️

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=ed...

AD/SB ID: 10409

Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: ATA 78 - ENGINE EXHAUST EJECTOR DUCT INSPECTION

Title/Subject: ASB 189-384 NEW ISSUE (EAD 2023-0149 PARA 1)