

TIC-A109E-23-0019

ENGINE 1

AD/SB ID: 11034 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOB	On Condition	-		0	-	-	Category 8

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=ed...

AD/SB ID: 11034 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: TURBOSHAFT ENGINE - RGB FRONT HOUSING ASSEMBLY - MODIFICATION OF

Title/Subject: SB NO. 28408, NEW ISSUE - ENGINE 1

ENGINE 2

AD/SB ID: 11035 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOB	On Condition	-		0	-	-	Category 8

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=ed...

AD/SB ID: 11035 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: TURBOSHAFT ENGINE - RGB FRONT HOUSING ASSEMBLY - MODIFICATION OF

Title/Subject: SB NO. 28408, NEW ISSUE - ENGINE 2