

TIC-AW189-23-0134

ADI/SB ID: 11145 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BCE	Not Applicable	-		0	-	-	NOT APPLICABLE
9M-BOF	Not Applicable	-		0	-	-	NOT APPLICABLE

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy.aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=e...

ADI/SB ID: 11145 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: Repetitive

Reference Number: ATA 24 - STARTER GENERATOR DRIVE SHAFT ASSEMBLY REPLACEMENT

Title/Subject: SB NO. 189-378 NEW ISSUE