


TIC-AW189-24-0023

ENGINE 1



| Aircraft | Based On | Period | Warning Unit | Warning | Last Done | Next Due | Status |
|----------|----------------|--------|--------------|---------|-----------|----------|----------------|
| 9M.BOE | Not Applicable | - | - | 0 | - | - | NOT APPLICABLE |
| 9M.BOF | Not Applicable | - | - | 0 | - | - | NOT APPLICABLE |


AD/SB ID: 11291

Type: ADS Repetitive

Reference Number: FAA - C17-281 EMERGENCY AIRWORTHINESS DIRECTIVES
TURBINE SECTION

Title/Subject: EAD NO 2024-05-51 NEW ISSUE - ENGINE 1

ENGINE 2



| Aircraft | Based On | Period | Warning Unit | Warning | Last Done | Next Due | Status |
|----------|----------------|--------|--------------|---------|-----------|----------|----------------|
| 9M.BOE | Not Applicable | - | - | 0 | - | - | NOT APPLICABLE |
| 9M.BOF | Not Applicable | - | - | 0 | - | - | NOT APPLICABLE |

AD/SB ID: 11292

Type: ADS Repetitive

Reference Number: FAA - C17-281 EMERGENCY AIRWORTHINESS DIRECTIVES
TURBINE SECTION

Title/Subject: EAD NO 2024-05-51 NEW ISSUE - ENGINE 2