

MODIFICATION

MODIFICATION STATUS LIST

Aircraft Registration:	9M-BOE	Serial No:	49045	Date:	01/04/2024	Page No:	1
Aircraft Hours:	1396:48	Landings:	2832.00	Engine 1:	1226:10	Engine 2:	1396:48

Type	Maintenance Required	Reference	Life At Install	Period	Last Done	Next Due	Remaining
GAM280/MD - INSTALLATION OF DOUBLER ON CENTRAL LOWER AFT FAIRING							
Modifications (Inspection)	INSTALLATION OF DOUBLER ON CENTRAL LOWER AFT FAIRING	GAM280/MD REV 0 DATED 24/11/2023		0 Months	19/02/2024	00/00/0000	0 Day
Date	INSTALLATION OF DOUBLER ON CENTRAL LOWER AFT FITTING - DOUBLER INSPECTION	GAM280/ICA REV 0 DATED 28 NOV 2023		24 Months	19/02/2024	19/02/2026	687 Days
Date	INSTALLATION OF DOUBLER ON CENTRAL LOWER AFT FITTING - FASTENERS INSPECTION	GAM280/ICA REV 0 DATED 28 NOV 2023		0 On Condition	-	-	-
GAM185/MD - ONE-TIME DEFERRAL OF DISPLAY UNIT REPLACEMENT							
Hours	ONE TIME DEFERRAL OF DISPLAY UNIT ON LEONARDO S.P.A AW189	CAAM APPROVAL MOD/A/2022/012, GAM185/MD, GAM185/ICA		30 Airframe Hours	1199:57	0:00	0:00 Hours
MD1380228 - INSTALLATION OF LOGO 9M REGISTRATION AND MALAYSIA FLAG ON AGUSTAWESTLAND AW189 (BOMBA)							
General	MD1380228, INSTALLATION OF LOGO, 9M REG AND MALAYSIAN FLAG	ICA 1380228 REV 0		0 On Condition	-	-	-
MD1380229 - INSTALLATION OF DATA PLATE ON AGUSTAWESTLAND AW189							
General	MD1380229, INSTALLATION OF DATA PLATE ON AW189	ICA 1380229 REV 0		0 On Condition	-	-	-
EOAS/189/19/001 - MAIN ROTOR BLADE REPAIR							
Hours	MAIN ROTOR BLADE REPAIR (INTEGRATED INTO 50 FH INSPECTION MI62-01)	EOAS/189/19/001 REV.0 (02 AUG 2019) & MI62-01 (50 FH INSPECTION)		50 Airframe Hours	0:00	1401:01	4:13 Hours
EOAS/189/19/002 - TAIL GEARBOX OUTPUT SHAFT REPAIR							
Date	1Y TAIL GEAR BOX OUTPUT SHAFT REPAIR (INTEGRATED IN 1Y AF INSP)	EOAS/189/19/002, REV. 1 (05 DEC 2019)		1 Years	01/08/2023	01/08/2024	120 Days
STC 10063214 - AIR AMBULANCE TECHNOLOGY							
Modifications (Inspection)	STC 10063214, STRETCHER INSTALLATION	MMS-AW189-EMS-002		0	0:00	0:00	