

TIC-AW139-24-0083

Edit Limitation (A/C: 9M-YTL)

Limitation EASA EAD NO.2024-0084-E, NEW ISSUE-ATA 32 -MAIN LANDING GEA...

Based On: Airframe Landings

Period: 7000

Warning: 50

Warning Unit: Landings

Last Done/Fitted: 0.00

Next Due: 7000.00

Limitation Notes:

REFER TIC-AW139-24-0083

COMPLIANCE: GROUP 2 HELICOPTER. WITHIN 100 FH AFTER THE AFFECTED PART ACCUMULATED 7000 LDGS AND THEN EVERY 2000 LDGS OR 12 MONTHS WHICHEVER OCCURS FIRST.

APPLICABLE DUE TO AIRCRAFT FITTED WITH MAIN SHOCK ABSORBER P/N 3G3210V01031.

CURRENT CYCLE SINCE NEW:

i) LH MAIN SA = 665 LANDING CYCLES

AD Number/Subject	Based On	Period	Warning	Last AD	Next AD	Remaining	History
EASA AD 2021-0044 REV 1 PARA (2) (ASB139-661 REV. B) ATA 32 -MAIN LANDING GEAR SHOCK ABSORBER -INSPECTION	Date (Months)*	12.0	3.0 Months	08/09/2023	07/09/2024	149 days	Complete
EASA AD 2021-0044 REV 1 PARA (2) (ASB139-661 REV. B) ATA 24 OVERHEAD PANEL INSPECTION PART II (300FH // 12M INSPECTION)	Airframe Hours*	300.0	50.0 Hours	409:40	709:40	273:42	Complete

General Log Book Inspections Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected

AD Number/Subject Based On Period Warning Last AD Next AD Remaining

REPETITIVE AD

AD Number/Subject	Based On	Period	Warning	Last AD	Next AD	Remaining	History
EASA EAD NO 2024-0084-E, NEW ISSUE ATA 32 -MAIN LANDING GEAR SHOCK ABSORBER -INSPECTION	Airframe Landings	7000.0	50.0 Landings	0.00	7000.00	6335.00	Complete

galaxy aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&opener_form_name=editform&template_id=11270&opener_aircraft_id=42

AD/SB ID: 11270

General Config List Aircraft List Task/Check List Linked To BOM

Type: ADS Repetitive

Reference/Number: ATA 32 -MAIN LANDING GEAR SHOCK ABSORBER -INSPECTION

Title/Subject: EASA EAD NO 2024-0084-E, NEW ISSUE

Version No:

Reason For Raising: