

# TIC-AW189-24-0049

## ENGINE 1

ADI/SB ID: 11556 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS  Repetitive

Reference Number: ENGINE - POWER TURBINE MODULE (72-50-00) - POWER TURBINE SHAFT /TORQUE REFERENCE TUBE MAGNETIC INSERT BRAZE INSPECTION

Title/Subject: ASB 72-A0034, REV 01 - ENGINE 1

ADI/SB ID: 11556 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BCE	Not Applicable	-		0	-	-	NOT APPLICABLE
9M-BOF	Not Applicable	-		0	-	-	NOT APPLICABLE

## ENGINE 2

ADI/SB ID: 11560 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS  Repetitive

Reference Number: ENGINE - POWER TURBINE MODULE (72-50-00) - POWER TURBINE SHAFT /TORQUE REFERENCE TUBE MAGNETIC INSERT BRAZE INSPECTION

Title/Subject: ASB 72-A0034, REV 01 - ENGINE 2

ADI/SB ID: 11560 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BCE	Not Applicable	-		0	-	-	NOT APPLICABLE
9M-BOF	Not Applicable	-		0	-	-	NOT APPLICABLE