

**AD 2022-0182-E PARA (7), (SBEA 139-725 REV.A PART IV)**

**9M-PMA**

Edit Limitation (A/C: 9M-PMA)

Edit Limitation AD 2022-0182-E PARA (7), (SBEA 139-725 REV.A PART IV)-ATA 6... Cancel Save

Based On: Airframe Hours

Warning: 50

Warning Unit: Hours

Completed: 1654.00

Due At: 0.00

Status: COMPLIED WITH

Limitation Notes: TIC-AW139-22-0179 DATED 31 AUGUST 2022  
TERMINATING ACTION ON PARA 7 OF THIS AD  
9M-PMA-14765 ON 11/03/2023 AT 1654:10FH

**9M-PMB**

Edit Limitation (A/C: 9M-PMB)

Edit Limitation AD 2022-0182-E PARA (7), (SBEA 139-725 REV.A PART IV)-ATA 6... Cancel Save

Based On: Airframe Hours

Warning: 50

Warning Unit: Hours

Completed: 1744.00

Due At: 0.00

Status: COMPLIED WITH

Limitation Notes: TIC-AW139-22-0179 DATED 31 AUGUST 2022  
TERMINATING ACTION ON PARA 7 OF THIS AD  
9M-PMB-12251 ON 04/08/2022 AT 1744:10FH

**9M-PMD**

Edit Limitation (A/C: 9M-PMD)

Edit Limitation AD 2022-0182-E PARA (7), (SBEA 139-725 REV.A PART IV)-ATA 6... Cancel Save

Based On: Airframe Hours

Warning: 50

Warning Unit: Hours

Completed: 1548.00

Due At: 0.00

Status: COMPLIED WITH

Limitation Notes: TIC-AW139-22-0179 DATED 31 AUGUST 2022  
TERMINATING ACTION ON PARA 7 OF THIS AD  
9M-PMD-14474 ON 10/03/2023 AT 1548:35FH (A3L 01257)

**9M-PME**

Edit Limitation (A/C: 9M-PME)

Edit Limitation AD 2022-0182-E PARA (10), (SBEA 139-725 REV.A PART IV)-ATA ...

Based On: Airframe Hours

Warning: 0

Warning Unit: Hours

Completed: 1610.58

Due At: 0.00

Status: COMPLIED WITH

Limitation Notes: TIC-AW139-22-0179 DATED 31 AUGUST 2022  
TERMINATING ACTION IS ON PARA 10 OF THIS AD  
9M-PME-16852 ON 09/11/2023 AT 1610:35FH (A3L 01825)

### 9M-PMF

Edit Limitation (A/C: 9M-PMF)

Edit Limitation AD 2022-0182-E PARA (10), (SBEA 139-725 REV.A PART IV)-ATA ...

Based On: Airframe Hours

Warning: 0

Warning Unit: Hours

Completed: 1106.42

Due At: 0.00

Status: COMPLIED WITH

Limitation Notes: TIC-AW139-22-0179 DATED 31 AUGUST 2022  
TERMINATING ACTION IS ON PARA 10 OF THIS AD  
CARRIED OUT 9M-PMF-17874 ON 19/03/2024 AT 1106:25FH

### 9M-JPM

Edit Limitation (A/C: 9M-JPM)

Edit Limitation AD 2022-0182-E PARA (10), (SBEA 139-725 REV.A PART IV)-ATA ...

Based On: Airframe Hours

Warning: 50

Warning Unit: Hours

Completed: 297.78

Due At: 0.00

Status: COMPLIED WITH

Limitation Notes: TIC-AW139-22-0179 DATED 31 AUGUST 2022  
TERMINATING ACTION IS ON PARA 10 OF THIS AD  
COMPLIED WITH REFER WP 9M-JPM-18002 AT 297:47 FH ON 12/2/24

Aeronet Galaxy Aerospace > Modifications > Edit - Google Chrome

galaxy.aeronet.nz/index.html?function=aircraft\_templates&opener\_name=aircraft&mode=edit&template=no&opener\_form\_name=e...

AD/SB ID: 10350

General Config List Aircraft List Task/Check List Linked To BOM

Type: ADS Repetitive

Reference/Number: ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT

Title/Subject: AD 2022-0182-E PARA (10), (SBEA 139-725 REV.A PART IV)

Version No:

Reason For Raising: