TIC-AS350-24-0115

				🗙 Cancel 📓 S 📥	
		ASB NO. AS350-05.00.90 REV 5-ATA 55 - TIME LI	MITS - MAINTE	Cancer (m a	
	Warning:				
	-			Version: 4.7.0	
2024 Airframe: 917:36	Completed:	· · ·			
ngine 1 Modifications ADs	Due At:	0.00			
	Status:	NOT APPLICABLE		Show N/A	
		TIC-AS350-24-0115			
	Limit dan Natasi		TO AIRCRAFT HAS BEEN EMBODIED WITH MOD 073148 DURING MANUFAC	CTURE.	
e E E	Limitation Notes:	COMPLIANCE: NOT APPLICABLE FOR COM	MPLIANCE.		
IG VALVE ASSEMBLY. INSPEC				792:06 Ø 1592:0	
👫 🕒 Aeronet Galaxy	🗅 Aeronet Galaxy Aerospace > Modifications >Edit - Personal 3 - Microsoft Edge — 🗆 🗙				
/f 🗇 https://ga	alaxyaerospace.	.aeronet.nz/index.html?function=	aircraft_templates&opener_name=aircraft&mode=edit&t	template=no&o ♀ A ^N	
ME AD/SB ID: 11706				🔀 Close 🕢 Update 📓 Save & Clos	
CH General Config List	t Aircraft List Task/	/Check List Linked To BOM			
Type :	SBS 🗸 🗌 Repeti	ütive			
		IMITS - MAINTENANCE CHECKS - UPPER	FIN INSPECTION OF		
	THE SPAR AND AT	TACHMENT SCREWS OF THE UPPER FIN			
Title/Subject:	EASB NO. AS350-05.0	00.90 REV 5			
Version No:					
Reason For Raising:					
ND URL:					
IAI		numbers only)			
Tolerance:	0 % (Whole r				
	Creep on Completion	Title	Filename	٥	
	+ \$	nue	Filenative	¥	

Figure 1: 9M-LKE AERONET HAS BEEN UPDATED