

TIC-AS350-24-0107

The image shows two overlapping windows from the Aeronet software. The top window is titled 'Edit Limitation (A/C: 9M-LKE)'. It contains the following fields:

- Based On: Select
- Warning: 0
- Warning Unit: Select
- Completed: -
- Due At: 0.00
- Status: NOT APPLICABLE
- Limitation Notes: TIC-AS350-24-0107
NOT APPLICABLE DUE TO MOD 073466 HAS BEEN EMBODIED.

The bottom window is a browser window titled 'Aeronet Galaxy Aerospace > Modifications > Edit - Personal 3 - Microsoft Edge'. The address bar shows the URL: https://galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no&o...

The browser window displays the 'AD/SB ID: 11708' page with the following details:

- General | Config List | Aircraft List | Task/Check List | Linked To | BOM
- Type: SBS Repetitive
- Reference Number: ATA 53 - FUSELAGE VISUAL CHECK FOR CRACKS IN THE LOWER CROSSBEAMS OF THE YAW CONTROL BELLCRANK SUPPORT
- Title/Subject: SB NO. 05.00.59 REV 2
- Version No: [Empty]
- Reason For Raising: [Empty]
- URL: [Empty]
- Date: [Empty]
- Tolerance: 0 % (Whole numbers only)
- Creep Type: Creep on Completion Unit
- Document: [Empty] Title [Empty] Filename [Empty]

Figure 1: 9M-LKE AERONET HAS BEEN UPDATED