## TIC-AS350-24-0097

OLS- TAIL SERVO-CONTROL	Edit Limitation (A/C: S	9M-LKE)	× -		-
- WEAR ON ROLLERS AND RA	Edit Limitation AD NO. 2007-0117-CN NEW ISSUE-ATA 72 CANCELLED - ENGINES F				
VIBRATION DAMPER & BLADE	- IN Based On:	Select			
H CHANGE PLATE BEARING S	PA Warning:	0			
IGS - BREEZE 450-LB ELECTRI	Warning Unit:	Select V			
OLS - CYCLIC STICK BOWL LO	Completed:				
BATTERY LUG CONNECTION	Due At:	0.00			
OLS - DOUBLE LOCKING OF ST	Status:	CANCELLED			
/ER - MODIFICATION		TIC-AS350-24-0097			
UCTURE JUNCTION FRAME		NOT APPLICABLE DUE TO AIRCRAFT FITTED WITH ARRIEL 2D ENGINE.	- 18		
ANCE CHECKS - REPLACEMEN	Limitation Notes:	THIS NOTICE CANCELS EASA AD 2007-0117.  COMPLIANCE: NOT APPLICABLE FOR COMPLIANCE.	- 11		
HYDRAULIC CUT-OFF FUNCTION	N-	COMPLIANCE: NOT APPLICABLE FOR COMPLIANCE.			
INGS Aeronet Galaxy	Aerospace > Mod	difications >Edit - Personal 3 - Microsoft Edge			×
0101	•	<del>-</del>			
ings 🖒 https://ga	alaxyaerospace.	.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&temp	late=no&o.	Q	Ψ»
ISSU AD/SB ID: 11351			⊠Close �Up	odate 🖫 Sa	we & Close
General Config Lis	t Aircraft List Task/	/Check List Linked To BOM			
CON Type :	ADS V Repet	itive			
AD 2 Reference/Number:	ATA 72 CANCELL	ED - ENGINES FORMERLY USED BY NON-CIVIL			
AD 2					
AD 2 Title/Subject:	AD NO. 2007-0117-CN NEW ISSUE				
AD 2 Version No:					
ISSU Reason For Raising:					
ISSU					
SSUE URL:					
ISSUI Date:					
Tolerance:		numbers only)			
Tolerance: CONT ISSU Creep Type:		numbers only)			

Figure 1: 9M-LKE AERONET HAS BEEN UPDATED