

TIC-AW139-24-0078

AD/ SB ID: 11762 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS Repetitive

Reference Number: ATA 32 - NLG SHOCK ABSORBER INSPECTION

Title/Subject: EASB NO. 139-783. NEW ISSUE

AD/ SB ID: 11762 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BOC	Not Applicable	-		0	-	-	NOT APPLICABLE
9M-BOD	Not Applicable	-		0	-	-	NOT APPLICABLE