

TIC-AW139-24-0028

AD/ SB ID: 11185 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS  Repetitive

Reference Number: ATA 21 - VENTILATION INSULATION IMPROVEMENT

Title/Subject: SB NO. 139-581, REVA

AD/ SB ID: 11185 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

| Aircraft | Based On       | Period | Warning Unit | Warning | Last Done | Next Due | Status         |
|----------|----------------|--------|--------------|---------|-----------|----------|----------------|
| 9M-BCC   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |
| 9M-BOD   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |
| 9M-JPM   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |
| 9M-PMA   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |
| 9M-PMB   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |
| 9M-PMD   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |
| 9M-PME   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |
| 9M-PMF   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |
| 9M-YTL   | Not Applicable | -      |              | 0       | -         | -        | NOT APPLICABLE |