

# TIC-AW139-24-0046

AD/SB ID: 11768 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Type: SBS  Repetitive

Reference Number: ATA 56 - CABIN STORM WINDOW LH-RH INSTALLATION

Title/Subject: SB NO. 139-657 NEW ISSUE

AD/SB ID: 11768 Close Update Save & Close

General | Config List | Aircraft List | Task/Check List | Linked To | BOM

Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
9M-BCC	On Condition	-		0	-	-	OPTIONAL
9M-BDD	Not Applicable	-		0	-	-	OPTIONAL