TIC-AW139-23-0366

_	F	dit Limitation (A/C: 9M-SAA S			25.0 Hours
					50.0 Hours
on No: RE		Edit Limitation SB NO. 139-526, REV. A-LEONARDO HELICOPTERS - AW139 SERVICE 🔀 Cancel 📓 Save			
on No: REV.B]		Based On:	Not Applicable		25.0 Hours
		Warning:	0		20.0110.012
		Warning Unit:	Select V		05.011
		Completed:	· ·		25.0 Hours
TION		Due At:	0.00		
ECTION		Status:	CANCELLED V		
H REPLA	CEMENT		TIC-AW139-23-0366		
REPLACEMENT					
		Limitation Notes:	APPLICABILITY: APPLICABLE TO AIRCRAFT TYPE REASON: THIS REVISION OF SB ISSUED TO INFORM IT IS CANCELLED. ITS TECHNICAL CO	ONTENT IS SUPERSEDED	
			BY AMPI SCHEDULED MAINTENANCE CHECK 63-20 (REF. DM 39-A-63-20-03-00A-310A-A) A CO63-06.	AND AMPI TIME LIMITS	Warning
			COMPLIANCE: FOR INFORMATION ONLY		
		alaw Aerospace > Mr	difications >Edit - Personal 3 - Microsoft Edge	- 0	×
TA 24 DI			-		
fttps://galaxyaerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&template=no& \bigcirc $A^{\mathbb{N}}$					
A D/SB ID: 11789					
TA 55 TA	General Co	onfig List Aircraft List	Task/Check List Linked To BOM		
TA 23 - F					
TA 21 EC			petitive		
TA 28 C	Reference/Nu	LEONARDO HEL	RDO HELICOPTERS - AW139 SERVICE BULLETIN ATA 63 MGB 🗔 🤤		
TA 95 - I			///////////////////////////////////////		
TA 93 VI	Title/Su	bject: SB NO. 139-526,	REV. A		
TA 53 - L	Versio	n No:			
TA 33 HE	Reason For Ra	ising:			
				4	
N		URL:			
		Date:	- 🗸 🔚		
COTION	Tolerance: 0% (Whole numbers only)				
ECTION:			Creep on Completion Unit		
_	Doou	ment: + 🌣	Title Filename		0

Figure 1: 9M-SAAS AERONET HAS BEEN UPDATED