

FAA AD NO. 2005-14-12, NEW ISSUE COMPLIANCE

9M-PTA-15839

Edit Limitation (A/C: 9M-PTA)

Edit Limitation FAA AD 2005-14-12-PROPELLER MOUNTING BOLTS (PROPELLER NO. 1...

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH AFFECTED PROPELLER MOUNTING BOLT SOURCE CODE AND MANUFACTURING LOT NUMBER. REFER 9M-PTA-15839-001 ON 09/06/2023 AT 6544:21 AFH

Edit Limitation (A/C: 9M-PTA)

Edit Limitation FAA AD 2005-14-12-PROPELLER MOUNTING BOLTS (PROPELLER NO. 2...

Based On: Select

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT NOT FITTED WITH AFFECTED PROPELLER MOUNTING BOLT SOURCE CODE AND MANUFACTURING LOT NUMBER. REFER 9M-PTA-15839-001 ON 09/06/2023 AT 6544:21 AFH

9M-PTB-15840

Edit Limitation (A/C: 9M-PTB)

Edit Limitation FAA AD 2005-14-12-PROPELLER MOUNTING BOLTS (PROPELLER NO. 1...

Based On: Airframe Hours

Warning: 0

Warning Unit: Hours

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO SOURCE CODE AND MANUFACTURING LOT NUMBER NOT AFFECTED
C/O: 9M-PTB-15840-001 ON 09/09/2023 AT 5986:35 AFH.
REFER TIC-B300-21-0059 DATED 11/10/2021.

Edit Limitation (A/C: 9M-PTB)

Edit Limitation FAA AD 2005-14-12-PROPELLER MOUNTING BOLTS (PROPELLER NO. 2...

Based On: Airframe Hours

Warning: 0

Warning Unit: Hours

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO SOURCE CODE AND MANUFACTURING LOT NUMBER NOT AFFECTED.
C/O: 9M-PTB-15840-001 ON 09/09/2023 AT 5986:35 AFH.
REFER TIC-B300-21-0059 DATED 11/10/2021.

9M-PTC-15841

Edit Limitation (A/C: 9M-PTC)

Edit Limitation FAA AD 2005-14-12-PROPELLER MOUNTING BOLTS (PROPELLER NO. 1...

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT INSTALLED WITH PROPELLER MOUNTING BOLT PART NUMBER B-3339 SOURCE CODE GS MANUFACTURING LOT NUMBER 106529, 106731.
REFER 9M-PTC-15841-001 ON 22/06/2023 AT 4272:31 AFH

Edit Limitation (A/C: 9M-PTC)

Edit Limitation FAA AD 2005-14-12-PROPELLER MOUNTING BOLTS (PROPELLER NO. 2...

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT INSTALLED WITH PROPELLER MOUNTING BOLT PART NUMBER B-3339 SOURCE CODE GS MANUFACTURING LOT NUMBER 117521.
REFER 9M-PTC-15841-001 ON 22/06/2023 AT 4272:31 AFH

9M-PTD-15842

Edit Limitation (A/C: 9M-PTD)

Edit Limitation FAA AD 2005-14-12-PROPELLER MOUNTING BOLTS (PROPELLER NO. 1... Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT IS FITTED WITH PROPELLERS MOUNTING BOLT PART NUMBER B-3339 SOURCE CODE GS MANUFACTURING LOT NUMBER 117521.
REFER 9M-PTD-15842-001 ON 12/06/2023 AT 1323:15 AFH.

Edit Limitation (A/C: 9M-PTD)

Edit Limitation FAA AD 2005-14-12-PROPELLER MOUNTING BOLTS (PROPELLER NO. 2... Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT IS FITTED WITH PROPELLERS MOUNTING BOLT PART NUMBER B-3339 SOURCE CODE GS MANUFACTURING LOT NUMBER 117521.
REFER 9M-PTD-15842-001 ON 12/06/2023 AT 1323:15 AFH.

9M-PTE-15843

Edit Limitation (A/C: 9M-PTE)

Edit Limitation FAA AD 2005-14-12-PROPELLER MOUNTING BOLTS (PROPELLER NO. 1... Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT FITTED WITH PROPELLER MOUNTING BOLT PART NUMBER B-3339 SOURCE CODE MSA AND MANUFACTURING LOT NUMBER 034.
REFER 9M-PTE-15843-001 ON 12/06/2023 AT 2387:15 AFH

Edit Limitation (A/C: 9M-PTE)

Edit Limitation FAA AD 2005-14-12-PROPELLER MOUNTING BOLTS (PROPELLER NO. 2... Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT FITTED WITH PROPELLER MOUNTING BOLT PART NUMBER B-3339 SOURCE CODE GS AND MANUFACTURING LOT NUMBER 106731.
REFER 9M-PTE-15843-001 ON 12/06/2023 AT 2387:15 AFH