

(A/C: 9M-PTA)

tion MTL-36-02 , NEW ISSUE-PNEUMATIC - FLOW CONTROL VALVE INSULA...

Cancel

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes:

NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER IS NOT AFFECTED.
REFER TIC-B300-24-0020 DATED 18/04/2024.

(A/C: 9M-PTB)

tion MTL-36-02 , NEW ISSUE-PNEUMATIC - FLOW CONTROL VALVE INSULA...

Cancel

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes:

NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER IS NOT AFFECTED.
REFER TIC-B300-24-0020 DATED 18/04/2024.

(A/C: 9M-PTC)

tion MTL-36-02 , NEW ISSUE-PNEUMATIC - FLOW CONTROL VALVE INSULA...

Cancel

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes:

NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER IS NOT AFFECTED.
REFER TIC-B300-24-0020 DATED 18/04/2024.

(A/C: 9M-PTD)

tion MTL-36-02 , NEW ISSUE-PNEUMATIC - FLOW CONTROL VALVE INSULA...

Cancel

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes:

NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER IS NOT AFFECTED.
REFER TIC-B300-24-0020 DATED 18/04/2024.

(A/C: 9M-PTE)

tion MTL-36-02 , NEW ISSUE-PNEUMATIC - FLOW CONTROL VALVE INSULA...

Cancel

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes:

NOT APPLICABLE DUE TO AIRCRAFT SERIAL NUMBER IS NOT AFFECTED.
REFER TIC-B300-24-0020 DATED 18/04/2024.