

Sesto Calende, 2023-02-09

LETTER OF TRANSMITTAL

To: Holders of AB139/AW139 Rotorcraft Flight Manual (EASA Approved)

Subject: Errata Corrige applicable to Issue 2 Revision 29, dated 25 January 2023

This Letter of Transmittal includes a copy of Errata Corrige applicable to AW139 Rotorcraft Flight Manual (EASA Approved) Issue 2 Revision 29, dated 25 January 2023.

Since the Record of Temporary Revisions (ROTR) was printed with a wrong date in the footer, please remove and discard the ROTR already received and replace it with the pages included in this Errata Corrige, with the footer dated 25-01-2023.

The new pdf of AW139 Rotorcraft Flight Manual (EASA Approved) Issue 2 Revision 29, comprehensive of the updated ROTR, was loaded on Leonardo Portal.

Best regards,
Customer Support & Service – Italy
Product Support Engineering

Leonardo - Società per azioni

Sede legale:

Piazza Monte Grappa, 4 - 00195 Roma - Italia

Tel. +39 06 324731 - Fax +39 06 3208621

Sede operativa:

Via Giovanni Agusta, 520 – 21017 Cascina Costa di Samarate (VA) – Italia

Tel. +39 0331 229111 - Fax +39 0331 229605

elicotteri@pec.leonardo.com

Cap. Soc. € 2,543,861,738.00 i.v.

C.F. e Registro Imprese di Roma n. 00401990585

P.I. 00881841001

R.E.A. n. 7031

RECORD OF TEMPORARY REVISIONS**ACTIVE TEMPORARY REVISIONS**

The following Temporary Revisions are still active and must be retained in your printed manual.

For Temporary Revisions, changes from the basic issue are printed in red.

TR N°	Page	Approval	Note
2-3	2-6, 2-9	EASA Approval N° R.A. 01396 dated 22 October 2007	–

INACTIVE TEMPORARY REVISIONS

The following Temporary Revisions are inactive and must not be retained in your printed manual:

TR N°	Page	Approval	Note
5-1	S11-8A, S11-8B, S11-21, S11-22, S11-24, S11-25	Approved with NDC-139G0257-026 P. EASA 10072085	Introduced with RFM Issue 2 Revision 25.
5-2	5-5A, 5-5, S52-iA, S52-i, S52-1A, S52-1, S52-6, S52-7	Approved with NDC-139G9350-010 dated 23 September 2020 under the authority of DOA ref. EASA.21J.005	Introduced with RFM Issue 2 Revision 27.
5-3	5-5A, 5-5, S52-iA, S52-i, S52-1A, S52-1, S52-2, S52-3, S52-4, S52-4A, S52-4B, S52-4C	Approved with NDC-139G9350-012 dated 28 May 2021 under the authority of DOA ref. EASA.21J.005	Introduced with RFM Issue 2 Revision 28.
5-4	5-2, 5-2A, S17-i, S17-iA, S17-1, S17-1A	Approved with NDC-139G0257-032 dated 20 January 2023 under the authority of DOA ref. EASA.21J.005	Introduced with RFM Issue 2 Revision 29.