

Sesto Calende (VA), 06 March 2023

LETTER OF TRANSMITTAL

**To: Holders of AW189 Rotorcraft Flight Manual (EASA Approved) Issue 2
Revision 11**

Subject: ERRATA CORRIGE - Supplement 4 (Category A operations)

This Errata Corrige is applicable both to the hard copies and to PDF files published on Leonardo Customer Portal.

For RFM hard copies discard Page S4C-4 already in your hands and replace it with the attached one.

For PDF Files already downloaded, replace them with the new files available on Leonardo Customer Portal. Since the affected page is applicable to all aircraft configurations, make sure to download RFM Volume applicable to all your Helicopter configurations.

Figure S4C-1 included within Page S4C-4 has been changed to reintroduce within RFM the correct Wind Limitations Chart.

Best regards,
Product Support Engineering.

Leonardo - Società per azioni

Sede legale:

Piazza Monte Grappa, 4 - 00195 Roma - Italia

Tel. +39 06 324731 Fax +39 06 3208621

Sede operativa:

via Indipendenza, 2 - 21018 Sesto Calende (VA) - Italia

Tel. +39 0331 915011 Fax +39 0331 915142

Cap. Soc. € 2.543.861.738,00 i.v.

C.F. e Registro Imprese di Roma n. 00401990585

P. I. 00881841001

R.E.A. Roma n. 7031