



WORK ORDER

To: MYCOPTER AVIATION SERVICES SDN.BHD

Address: Lot 10, Helicopter Centre, Malaysia International Malaysia	Work Order Number: GAM-WO-HFA-21-058
Attention: Syahrn Nizam Bin Abdul Rahman Engineering Manager syahrn.nizam@mycopteraviation.com.my	Work PackReference: WP-HFA-21-058
	Date Issued: 06/01/2021
	A/C Registration / SN: 9M-HFA/1487
	Sheet: 1 of 1

Item	Description/Task/Inspection	Reference	Man Hours
1	(AD NO. 2020-0015) ASB EC120-53A017		PLEASE ADVISE

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
 Best Regards,

Zaty Nadhira Mohamed Zuhari
 Continuing Airworthiness Manager
 Email: zaty@galxyaerospace.my

CLIENT/OWNER: HELANG FLYING ACADEMY SDN. BHD. AIRCRAFT TYPE: EC120 B REGISTRATION: 9M-HFA BASE/FACILITY: WMSA DATE IN: OUT:		SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO: WP-HFA-21-058-001
	AIRCRAFT	1487				WORK/INSP/DESC: ASB EC120-53A017
	#1 ENGINE:	34553		N/A	N/A	WORKPACK REF: WP-HFA-21-058
	#2 ENGINE:	NIL		N/A	N/A	LBE REF NO.: N/A
				NG / N1	NF / N2	SHEET: 1 OF 1

Reason for raising: AD NO. 2020-0015 / ASB EC120-53A017 COMPLIANCE TO BE CARRIED OUT	Raised by and date: CAMO 06/01/2021	Other requirements/information: NIL
---	---	--

Item	Description	Technician	* Eng. CRS	Date
1	PROTECTIVE MEASURE - FUSELAGE - REAR FUSELAGE CORROSION ON THE TAIL BOOM TO PERFORM A CHECK FOR CORROSION AND CRACKS AT THE VHF ANTENNA ATTACHMENTS ON THE TAIL BOOM REF: AD NO. 2020-0015 // ASB NO. EC120-53A017, REVISION 1 REMARKS:			

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK ✓ WHERE APPLICABLE

PARTS LABELED & RETURNED	D.D. RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHT TEST	TORQUE CHK.	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D.D. STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	OEM/COMP LOG CARD	MOD.RECORD BOOK
--------------------------	-------------	-----------------	------------	-------------	-------------	----------------------	------------------	-------------------	--------------	---------------	-------------	-------------------	-----------------	--------------------	----------	-------------------	-----------------

CLIENT/OWNER: HELANG FLYING ACADEMY SDN. BHD. AIRCRAFT TYPE: EC120 B REGISTRATION: 9M-HFA BASE/FACILITY: WMSA DATE IN: OUT:	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO:	WP-HFA-21-058-001
	AIRCRAFT	1487			WORK/INSP/DESC:	PROTECTIVE MEASURE -
	#1 ENGINE:	34553	N/A	N/A	WORKPACK REF:	WP-HFA-21-058
	#2 ENGINE:	NIL	N/A	N/A	LBE REF NO.:	
				NG / N1	NF / N2	SHEET: 1 OF 1

Reason for raising: AD NO. 2020-0015 / ASB EC120-53A017 COMPLIANCE TO BE CARRIED OUT	Raised by and date: CAMO 06/01/2021	Other requirements/information: NIL
---	---	--

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					

NAME	FIRM	SIGN & APPROVAL	DATE

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK ✓ WHERE APPLICABLE

PARTS LABELLED & RETURNED	D.D. RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHT TEST	TORQUE CHK.	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D.D. STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	OEM/COMP LOG CARD	MOD RECORD BOOK
---------------------------	-------------	-----------------	------------	-------------	-------------	----------------------	------------------	-------------------	--------------	---------------	-------------	-------------------	-----------------	--------------------	----------	-------------------	-----------------