GalaxyAerospace	.	TE/	CUNICAL INCT	DH	CTION COMPLIA	. NI	CE	TIC REF N	0	TIC-AW139-23-0239	
maintenance . repair , overhaul			CHNICAL INST	KU	TION COMPLIA	NI A	ICE	DATE ISSU	JE	10 JUL 2023	
A. TECHNICAL PU	BLICA	ATIO	N (To Fill Up as Ne	cessa	ary)						
PUBLICATION TITLE	LEONARDO HELICOPTER - AW139 TEMPORARY MAINTENANCE INSTRUCTION  N TITLE										
	ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452 REPLACEMENT PROCEDURE										
	TMI 139-475						REV. DATE			16 JUN 2023	
REV NO	REV.F										
	✓ AC TYPE:				✓ AC S/N:			NG. TYPE:		□ ENG. S/N:	
	AW139				41358						
					31807						
					31726						
					31809						
APPLICABLE TO					31855						
					31913 31289 31291						
					31899 31903						
					31903						
		PR	OPELLER TYPE:	[	☐ PROPELLER S/N:			APU TYPE:		☐ APU S/N:	
☐ COMPONENT:				☐ EQUIPMENT:							
DISTRIBUTIONS	Ø	PER	ATOR ZAMO		<b>☑</b> CAMO		□Q	UALITY		OTHER:	
B. TECHNICAL SEF	RVICE	(Ар	plicability review p	rior to	o sentencing as nece	ess	ary)				
TIME LIMIT IMPOSED			ONE TIME INSPECTION		REPETITIVE INSPECTION		] OPTIONAL	L REQUIREMENT		MODIFICATION REQUIRED	
SPECIAL TOOLS REQU	IRED	INFORMATION ONLY			NOT APPLICABLE		OTHER:				
REMARKS:						NAME SIGNATURE & DATE					
41358 - APPLICABILIT REINFORCEMENT P/I					FITTED WITH ENGINE L	_H/	RH				
	IE LH/I				STRUCTIONS AND REC 33A15352 / 3P5333A154				1	$\widehat{I_0}$	
COMPLIANCE: FOR IN	NFORM	ЛАТІО	ON ONLY						NEL	HAMMAD IHSAN MASRI	
TOOLS/SPARES: NIL										14 JUL 2023	

Page 1 of 4 GAM/CAMO-001R2

31807 - APPLICABILITY: APPLICABLE TO AIRCRAFT WHEN FITTED WITH ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452

REASON: THIS TMI IS ISSUED TO PROVIDE UPDATE TO INSTRUCTIONS AND REQUIREMENTS TO REPLACE THE ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352/3P5333A15452. THE TMI WILL EXPIRE ON 16/6/2024

COMPLIANCE: FOR INFORMATION ONLY

TOOLS/SPARES: NIL

31726 - APPLICABILITY: APPLICABLE TO AIRCRAFT WHEN FITTED WITH ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452

REASON: THIS TMI IS ISSUED TO PROVIDE UPDATE TO INSTRUCTIONS AND REQUIREMENTS TO REPLACE THE ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452. THE TMI WILL EXPIRE ON 16/6/2024

COMPLIANCE: FOR INFORMATION ONLY

TOOLS/SPARES: NIL

31809 - APPLICABILITY: APPLICABLE TO AIRCRAFT WHEN FITTED WITH ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452

REASON: THIS TMI IS ISSUED TO PROVIDE UPDATE TO INSTRUCTIONS AND REQUIREMENTS TO REPLACE THE ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452. THE TMI WILL EXPIRE ON 16/6/2024

COMPLIANCE: FOR INFORMATION ONLY

TOOLS/SPARES: NIL

31855 - APPLICABILITY: APPLICABLE TO AIRCRAFT WHEN FITTED WITH ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452

REASON: THIS TMI IS ISSUED TO PROVIDE UPDATE TO INSTRUCTIONS AND REQUIREMENTS TO REPLACE THE ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452. THE TMI WILL EXPIRE ON 16/6/2024

COMPLIANCE: FOR INFORMATION ONLY

TOOLS/SPARES: NIL

31913 - APPLICABILITY: APPLICABLE TO AIRCRAFT WHEN FITTED WITH ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452

REASON: THIS TMI IS ISSUED TO PROVIDE UPDATE TO INSTRUCTIONS AND REQUIREMENTS TO REPLACE THE ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452. THE TMI WILL EXPIRE ON 16/6/2024

COMPLIANCE: FOR INFORMATION ONLY

TOOLS/SPARES: NIL

Page 2 of 4 GAM/CAMO-001R2

31289 - APPLICABILITY: APPLICABLE TO AIRCRAFT WHEN FITTED WITH ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452 REASON: THIS TMI IS ISSUED TO PROVIDE UPDATE TO INSTRUCTIONS AND REQUIREMENTS TO REPLACE THE ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452. THE TMI WILL EXPIRE ON 16/6/2024 COMPLIANCE: FOR INFORMATION ONLY TOOLS/SPARES: NIL 31291 - APPLICABILITY: APPLICABLE TO AIRCRAFT WHEN FITTED WITH ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452 REASON: THIS TMI IS ISSUED TO PROVIDE UPDATE TO INSTRUCTIONS AND REQUIREMENTS TO REPLACE THE ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452. THE TMI WILL **EXPIRE ON 16/6/2024** COMPLIANCE: FOR INFORMATION ONLY TOOLS/SPARES: NIL 31899 - APPLICABILITY: APPLICABLE TO AIRCRAFT WHEN FITTED WITH ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452 REASON: THIS TMI IS ISSUED TO PROVIDE UPDATE TO INSTRUCTIONS AND REQUIREMENTS TO REPLACE THE ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452. THE TMI WILL EXPIRE ON 16/6/2024 COMPLIANCE: FOR INFORMATION ONLY TOOLS/SPARES: NIL 31903 - APPLICABILITY: APPLICABLE TO AIRCRAFT WHEN FITTED WITH ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452 REASON: THIS TMI IS ISSUED TO PROVIDE UPDATE TO INSTRUCTIONS AND REQUIREMENTS TO REPLACE THE ENGINE LH/RH REINFORCEMENT P/N 3P5333A15352 / 3P5333A15452. THE TMI WILL EXPIRE ON 16/6/2024 COMPLIANCE: FOR INFORMATION ONLY TOOLS/SPARES: NIL C. CONTINUING AIRWORTHINESS MANAGEMENT (CAM) MANAGER / DEPUTY COMPONENT SEND OFF FOR COMPLIANCE MAINTENANCE SCHEDULE AMENT. PUBLICATION AMENDMENT PRE-PLANNED WORKSHEET П  $\Box$  $\Box$ REMARKS: NAME SIGNATURE & DATE 1) TECH PUB TO UPDATE THE TECHNICAL LIBRARY AND DISTRIBUTE TO ALL CONTROLLED PUBLICATION HOLDERS. AMIR ABDULLAH 17 JUL 2023

Page 3 of 4 GAM/CAMO-001R2

D. CAMO PLANNER						
	ENTRY TO MAINT. FORECAST		PREPARE WORK PACKAGE		PLAN EMBODIMENT	
	SPARE ORDER		MANPOWER QUALIFICATION		TOOLING	
	MARKS:  DISTRIBUTE AS INFO ONLY.				NAME SIGNATURE & DATE	

TIC COMPLIANCE CHECKLIST BY CAM MANAGER (Tick and Fill up as necessary)						
COMPLIANCE		REMARKS:	NAME			
YES	NO	TMI 139-475 REV F DISTRIBUTED AND UPDATED FOR ALL CONTROLLED HOLDER. REFER ATTACHED EMAIL DISTRIBUTION	SIGNATURE & DATE			
•		DATED 11.07.2023.	The state of the s			
			ZATY NADHIRA MOHAMED ZUHARI 22 AUG 2023			

Page 4 of 4 GAM/CAMO-001R2