


**A. TECHNICAL PUBLICATION (To Fill Up as Necessary)**

PUBLICATION TITLE	AIRBUS HELICOPTERS - EC120B SERVICE BULLETIN		
	PROTECTIVE MEASURE - FIRE PROTECTION - HAND FIRE EXTINGUISHER (HFE) - CHECK OF THE ABSENCE OF DISCHARGE OF THE HFE		
REV NO	SB NO. EC120-26-002, REV. 0	REV. DATE	24 NOV 2022
APPLICABLE TO	<input checked="" type="checkbox"/> AC TYPE:	<input checked="" type="checkbox"/> AC S/N:	<input type="checkbox"/> ENG. TYPE:
	EC120B	1275 1487 1089	
	<input type="checkbox"/> PROPELLER TYPE:	<input type="checkbox"/> PROPELLER S/N:	<input type="checkbox"/> APU TYPE:
	<input type="checkbox"/> COMPONENT:	<input type="checkbox"/> EQUIPMENT:	
DISTRIBUTIONS	<input checked="" type="checkbox"/> OPERATOR	<input checked="" type="checkbox"/> AMO	<input checked="" type="checkbox"/> CAMO
	<input type="checkbox"/> QUALITY		<input type="checkbox"/> OTHER:

**B. TECHNICAL SERVICE (Applicability review prior to sentencing as necessary)**

<input type="checkbox"/> TIME LIMIT IMPOSED	<input type="checkbox"/> ONE TIME INSPECTION	<input checked="" type="checkbox"/> REPETITIVE INSPECTION	<input type="checkbox"/> OPTIONAL REQUIREMENT	<input type="checkbox"/> MODIFICATION REQUIRED
<input type="checkbox"/> SPECIAL TOOLS REQUIRED	<input type="checkbox"/> INFORMATION ONLY	<input checked="" type="checkbox"/> NOT APPLICABLE	<input type="checkbox"/> OTHER:	

<p>REMARKS:</p> <p>1275 - APPLICABILITY: NOT APPLICABLE DUE TO AFFECTED ITEM NOT FITTED TO AIRCRAFT.</p> <p>REASON FOR ISSUANCE: THIS SB IS ISSUED TO PROVIDE INSTRUCTION AND GUIDELINES TO DETECT THE PRESENCE OF DISCHARGE OF THE HFE.</p> <p>COMPLIANCE: NOT TO COMPLY</p> <p>ACTION REQUIRED: 1. AERONET TO BE UPDATED. 2. TO DISTRIBUTE AS INFORMATION ONLY</p>	<p style="text-align: center;">NAME SIGNATURE &amp; DATE</p> <div style="text-align: center;">               MUHAMMAD IHSAN MASRI              2 DEC 2022         </div>
--	---

1487 - APPLICABILITY:  
NOT APPLICABLE DUE TO AFFECTED ITEM NOT FITTED TO AIRCRAFT.

REASON FOR ISSUANCE:  
THIS SB IS ISSUED TO PROVIDE INSTRUCTION AND GUIDELINES TO DETECT THE PRESENCE OF DISCHARGE OF THE HFE.

COMPLIANCE:  
NOT TO COMPLY

ACTION REQUIRED:  
1. AERONET TO BE UPDATED.  
2. TO DISTRIBUTE AS INFORMATION ONLY

1089 - APPLICABILITY:  
APPLICABLE TO THIS AIRCRAFT DUE TO AFFECTED ITEM FITTED TO AIRCRAFT.

REASON FOR ISSUANCE:  
THIS SB IS ISSUED TO PROVIDE INSTRUCTION AND GUIDELINES TO DETECT THE PRESENCE OF DISCHARGE OF THE HFE.

COMPLIANCE:  
RECOMMENDED TO COMPLY WITH THE SB BEFORE NEXT YEARLY WEIGHT CHECK.

ACTION REQUIRED:  
1. AERONET TO BE UPDATED.  
2. TO DISTRIBUTE TO AUTHORISED PUBLICATION HOLDER.

**C. CONTINUING AIRWORTHINESS MANAGEMENT (CAM) MANAGER / DEPUTY**

<input type="checkbox"/> MAINTENANCE SCHEDULE AMENT.	<input type="checkbox"/> PUBLICATION AMENDMENT	<input checked="" type="checkbox"/> PRE-PLANNED WORKSHEET	<input type="checkbox"/> COMPONENT SEND OFF FOR COMPLIANCE
--	--	---	--

REMARKS:

- 1) TO UPDATE SB SENTENCING FOR 9M-GAS IN AERONET AND MOD REC BOOK FOR MONITORING AND COMPLIANCE.
- 2) TO UPDATE SB SENTENCING FOR OTHER AIRCRAFT IN AERONET AND MOD REC BOOK FOR REFERENCE AND RECORD.

NAME  
SIGNATURE & DATE




AMIR ABDULLAH

30 JAN 2023

**D. CAMO PLANNER**

<input checked="" type="checkbox"/>	ENTRY TO MAINT. FORECAST	<input type="checkbox"/>	PREPARE WORK PACKAGE	<input type="checkbox"/>	PLAN EMBODIMENT
<input type="checkbox"/>	SPARE ORDER	<input type="checkbox"/>	MANPOWER QUALIFICATION	<input type="checkbox"/>	TOOLING

REMARKS:  SB UPDATED IN AERONET.	NAME SIGNATURE & DATE    ZULKARNAEN IBRAHIM  4 MAR 2023
--	---

**TIC COMPLIANCE CHECKLIST BY CAM MANAGER (Tick and Fill up as necessary)**

COMPLIANCE		REMARKS:	NAME SIGNATURE & DATE
YES	NO		
		AERONET UPDATED FOR MONITORING AND COMPLIANCE AND FOR REFERENCE AND RECORD.	AMIR ABDULLAH  5 MAR 2023