



| Publ. number  | Issue Date | TC Holder                    | Type                          | Subject   |
|---------------|------------|------------------------------|-------------------------------|---|
| US-2024-02-51 | 2024-01-06 | BOEING                       | 737                           | Doors - Mid-Cabin Door Plug - Inspection  |
| 2024-0003     | 2024-01-05 | AIRBUS S.A.S.                | A300-600, A300-600ST (Beluga) | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Part 4 / System Equipment Maintenance Requirements - Amendment |
| 2024-0004     | 2024-01-05 | LEONARDO S.p.A. HELICOPTERS  | A109/A119                     | Fuselage - Centre Fuselage Frame Assembly - Inspection / Repair / Modification  |
| 2024-0005     | 2024-01-05 | AIRBUS S.A.S.                | A350                          | Time Limits / Maintenance Checks - Damage Tolerant Airworthiness Limitation Items - ALS Part 2 - Amendment                            |
| 2024-0002     | 2024-01-04 | CFM INTERNATIONAL            | CFM56-5B, CFM56-5C, CFM56-7B  | Engine - High-Pressure Turbine Inner Stationary Seal - Inspection   |
| 2024-0001     | 2024-01-04 | AIRBUS S.A.S.                | A310                          | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Part 4 / System Equipment Maintenance Requirements - Amendment |
| CF-2023-79    | 2024-01-03 | MHI RJ Aviation ULC          | CL-600 (Regional Jet)         | Equipment / Furnishings - Overhead Storage Compartments - Improvement of the Overhead Bin Harnesses over the Class Divider            |
| US-2023-24-04 | 2024-01-03 | HONEYWELL INTERNATIONAL INC. | AS907                         | Engine / Engine Controls - Electronic Control Unit / Software - Replacement   |