



Publ. number	Issue Date	TC Holder	Type	Subject
US-2021-26-06	2022-01-21	GENERAL ELECTRIC	GE90	Engine - Transfer Gearbox Radial Gearshaft - Inspection / Replacement
2022-0011	2022-01-21	AIRBUS	A350	Wings - Upper / Lower Wing Skin Cover Edge Glow Sealant - Inspection / Modification
2022-0010	2022-01-20	LEONARDO S.p.A. HELICOPTERS	AW189	Navigation - Glide Slope Antenna - Inspection / Cleaning / Replacement
US-2022-02-16	2022-01-19	BOEING	787	Aircraft Flight Manual - Limitations / Operating Procedures - Amendment / Navigation - Minimum Equipment List - Amendment
US-2021-26-09	2022-01-19	BRANTLY HELICOPTERS INDUSTRIES U.S.A. Co., Ltd., ORPHANED (No TC Holder)	305, BRANTLY	Tail Rotor - Tail Rotor Hub - Inspections / Removal
US-2021-26-19	2022-01-19	GENERAL ELECTRIC	CF34-8	Engine - High Pressure Turbine Rotor Stage 1 Disk - Replacement
2022-0009	2022-01-19	CFM INTERNATIONAL	LEAP-1A/-1C	Engine - High Pressure Turbine Rotor Stage 1 Blade and Stator Stage 1 Nozzles - Inspection
2022-0008	2022-01-19	GE AVIATION CZECH	H75, H80, H85	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2022-0007	2022-01-19	CFM INTERNATIONAL	LEAP-1A/-1C	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Implementation
BR-2021-11-01R1	2022-01-18	EMBRAER	EMB-545/-550 (Legacy 500)	Equipment / Furnishings - Divan Shroud / Sideledge Panel Fairing - Installation
ISR-I-57-2021-12-4	2022-01-17	GULFSTREAM (GALP)	G200	Wings - Flaps Fairing Seal - Repair
ISR-I-57-2021-12-3	2022-01-17	GULFSTREAM (GALP)	G150	Wings - Flaps Fairing Seal - Repair
US-2020-03-11	2022-01-14	BOEING	707, 720	Fuel - Fuel Quantity Indicating System - Modification
US-2019-23-04	2022-01-14	BOEING	727	Fuel - Fuel Quantity Indicating System - Modification
US-2021-26-17	2022-01-13	BOEING	737	Equipment / Furnishings - Passenger Service Units and Life Vest Panels - Inspection / Modification
US-2022-02-02	2022-01-13	BELL TEXTRON INC. (BTI)	204B, 205, 210, 212	Main Rotor - Hub Strap Pins - Replacement
US-2021-24-14	2022-01-12	BOEING	787	Engine Exhaust - Thrust Reverser Translating Sleeve Secondary Sliders - Check / Replacement
US-2022-02-05	2022-01-12	PRATT & WHITNEY	PW1500G, PW1900G	Engine - High Pressure Turbine Stage 1/2 Disks - Replacement
2021-0184R2	2022-01-12	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Tail Rotor - Tail Gearbox Angular Clearance - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2022-01	2022-01-12	AIRBUS CANADA LP	BD-500 (A220 Series)	Placards and Markings - Elevator and Rudder Surface Rigging Inaccuracy Resulting from Flight Control Decal Positional Offset
2022-0004	2022-01-11	AIRBUS	A300	Fuselage - Aft Flight Compartment Window Rear Lower Corner and Fuselage Skin - Inspection
2022-0005	2022-01-11	SAFRAN HELICOPTER ENGINES	ARRIUS 1	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
US-2021-19-15	2022-01-10	BOEING	777	Equipment / Furnishings - Galley Mounted Attendant Seat Fittings - Modification